






1 2-2014 caulking existed



2 3-2014 metal pipe jacks





- 4 5-2014 very good duration shingle existed



5

6-bird block soffit flashing

Date Taken: 10/8/2024



6 7-caulking as existed

Date Taken: 10/25/2024



7

8-color starter as existed on
headwall nailed o

Date Taken: 6/24/2024



8 9-electrical disconnect vent remove Date Taken: 10/8/2024



9

10-gable cornice return

Date Taken: 6/24/2024



- 10 11-hand stock and special delivery
shingles




- 11 12-hand stock shingle to prevent
driveway damage



12 13-haul away with light weight
rubber tire contr Date Taken: 10/8/2024



13 14-high profile ridge as existed Date Taken: 6/24/2024



14 15-high profile ridge was existing Date Taken: 10/8/2024



15 16-kickout flashings as existed Date Taken: 10/8/2024



16 17-paint trim front window

Date Taken: 6/24/2024



17 18-paint trim left elevation(1) Date Taken: 6/24/2024




18 19-paint trim left elevation

Date Taken: 6/24/2024



19 20-primed painted vents caps
collars

Date Taken: 10/8/2024



20

21-rake ice water as existed

Date Taken: 10/8/2024



21 22-reuse reseal anchors

Date Taken: 10/8/2024



22 23-roofer hours to renail siding Date Taken: 10/25/2024



23 24-silicone and flashing under
soffite vent as e

Date Taken: 10/25/2024



24 25-silicone pipe jacks as existed Date Taken: 10/25/2024




25 26-site supervisor verify vent
install or HVAC m

Date Taken: 10/8/2024



26 27-split boot to seal roof anchors Date Taken: 10/25/2024



27 28-starter in valley color shingle Date Taken: 6/24/2024



28 1-water soak decking replace Date Taken: 10/8/2024