



Alan Podvin &lt;alan@acpstormrepair.com&gt;

---

**EagleView Report 15833335 - 11411 Switzer Park Pl, Parker, CO (Premium, \$55.00, 2525 sq ft)**

3 messages

---

**customerservice@eagleview.com** <customerservice@eagleview.com>  
To: alan@acpstormrepair.com  
Cc: alan@acpstormrepair.com

Fri, Sep 23, 2016 at 12:20 PM

Information regarding your EagleView order.

 [www.eagleview.com](http://www.eagleview.com)

Hello Alan,

Your **EagleView Measurement is ready** for the following order:**Report:** 15833335 (Premium, \$55.00, 2525 sq ft)**Address:** 11411 Switzer Park Pl, Parker, CO 80138-3009

Your completed EagleView report is attached to this email.


If we can help with any questions or concerns please contact us at [customerservice@eagleview.com](mailto:customerservice@eagleview.com). You may also speak with a live operator using our chat function at [www.eagleview.com](http://www.eagleview.com), or by calling 1-866-659-8439.

Thank you for choosing EagleView Technologies.

Sincerely,  
EagleView Customer Service [Have You Tried QuickSquares? Click To Learn More](#)We value your opinion and would love to hear [your feedback](#).1.866.659.8439 | [EagleView.com](http://EagleView.com)

EagleView Technologies, Inc. | 3700 Monte Villa Parkway Suite 200 | Bothell, WA 98021

Copyright © 2016 EagleView Technologies - All rights reserved.



Alan Podvin <alan@acpstormrepair.com>

Tue, Apr 10, 2018 at 6:58 PM

To: CustomerService <customerservice@eagleview.com>, Alan Podvin <alan@acpstormrepair.com>

Hi,

I have problem with this report. The measurements are wrong. Would you mind to correct it?

Please, see attached picture showing roof facet G is a pergola not roof.

Also roof slope D does not have step flashing, there is drip edge.

[Quoted text hidden]

--

**Thank You Very Much,**

*Alan C Podvin Jr*

**ACP Storm Repair LLC**

**303-351-2022** Direct to Alan

**800-648-1509** Office and Fax

**ACP Storm Repair.com**

**"The StormEraser" .com**

**Legal Disclaimer:**

This communication may contain information that is legally privileged, confidential or exempt from disclosure. It is for use only of the intended recipient to be used for purposes beneficial to ACP Storm Repair, ACP clients and ACP subsidiaries. Regardless whether you are the intended recipient or not, please note that any dissemination, distribution, copying or use other than stated above of information contained in this communication is strictly prohibited. If you received this message in error, please notify the sender by telephone or by return e-mail and delete it from the computer that received it in error.

**Note to Adjusters**, claim reps and other representatives of insurance companies: Please take notice that ACP is in communication as a contractor completing and collecting on wonderfully orchestrated code approved work and to explain, provide documentation, and collect what is fair to be paid under the terms of the insureds policies on said work. ACP reserves the right to document by any means possible all communications with insurance representatives. All information obtained may be used for collection and possible prosecution purposes.

**Note to Clients**, ACP Storm repair is a contractor completing repairs only. ACP Storm Repair representatives are not Public adjusters. ACP Storm Repair representatives are not legal advisers. Any legal advice given, quoted, spoken of or referenced to is as advisement of future possible actions ACP Storm will be taking in team with our clients against insurance companies and their representatives in the event a claim is not paid properly. Therefore legalese is used is not advice but preparation for possible events against insurance companies. Please consult with an attorney on applicability of any quoted laws, bills, acts or policy terms. Regardless ACP Storm always acts in unison and in the best interests of our clients to complete the repairs the best possible way.

**2 attachments**



**west view - roof slope G is a pergola..jpg**

4305K

**east view - roof slope D does not have step flashing, this is drip edge.jpg**

4330K



---

**customerservice@eagleview.com** <customerservice@eagleview.com>  
To: "alan@acpstormrepair.com" <alan@acpstormrepair.com>

Wed, Apr 11, 2018 at 3:18 AM

Thank you for contacting EagleView Technologies.

We have submitted this report for correction based on your notes.

Please let us know if there is anything else we can do to assist you. Our Customer Service department can be reached seven days a week at 1-866-659-8439, 6am-6pm Pacific time.

Thanks for choosing EagleView Technologies.

Kevin Rouse  
Customer Service Representative  
866-659-8439  
CustomerService@EagleView.com

----- Original Message -----

**From:** Alan Podvin [alan@acpstormrepair.com]

**Sent:** 4/10/2018 3:58 PM

**To:** customerservice@eagleview.com; alan@acpstormrepair.com

**Subject:** Re: EagleView Report 15833335 - 11411 Switzer Park Pl, Parker, CO (Premium, \$55.00, 2525 sq ft)

Hi,

I have problem with this report. The measurements are wrong. Would you mind to correct it?

Please, see attached picture showing roof facet G is a pergola not roof.  
Also roof slope D does not have step flashing, there is drip edge.

On Fri, Sep 23, 2016 at 10:20 AM, <customerservice@eagleview.com> wrote:

Information regarding your EagleView order.

[Inline image URL : [http://www.eagleview.com/evimages/ev\\_top.jpg](http://www.eagleview.com/evimages/ev_top.jpg)]

Hello Alan,

Your **EagleView Measurement is ready** for the following order:

**Report:** 15833335 (Premium, \$55.00, 2525 sq ft)

**Address:** 11411 Switzer Park Pl, Parker, CO 80138-3009

Your completed EagleView report is attached to this email.

If we can help with any questions or concerns please contact us at [customerservice@eagleview.com](mailto:customerservice@eagleview.com). You may also speak with a live operator using our chat function at [www.eagleview.com](http://www.eagleview.com), or by calling 1-866-659-8439.

Thank you for choosing EagleView Technologies.

Sincerely,  
EagleView Customer Service

[Inline image URL : <http://www.eagleview.com/images/QS-Email-File.png>]

We value your opinion and would love to hear [your feedback](#).

1.866.659.8439 | [EagleView.com](http://EagleView.com)

EagleView Technologies, Inc. | [3700 Monte Villa Parkway Suite 200](#) | [Bothell, WA 98021](#)

Copyright © 2016 EagleView Technologies - All rights reserved.

--  
**Thank You Very Much,**

*Alan C Podvin Jr*

**ACP Storm Repair LLC**  
**303-351-2022** Direct to Alan  
**800-648-1509** Office and Fax  
**ACP Storm Repair.com**

**"The StormEraser" .com**

**Legal Disclaimer:**

This communication may contain information that is legally privileged, confidential or exempt from disclosure. It is for use only of the intended recipient to be used for purposes beneficial to ACP Storm Repair, ACP clients and ACP subsidiaries. Regardless whether you are the intended recipient or not, please note that any dissemination, distribution, copying or use other than stated above of information contained in this communication is strictly prohibited. If you received this message in error, please notify the sender by telephone or by return e-mail and delete it from the computer that received it in error.

**Note to Adjusters**, claim reps and other representatives of insurance companies: Please take notice that ACP is in communication as a contractor completing and collecting on wonderfully orchestrated code approved work and to explain, provide documentation, and collect what is fair to be paid under the terms of the insureds policies on said work. ACP reserves the right to document by any means possible all communications with insurance representatives. All information obtained may be used for collection and possible prosecution purposes.

**Note to Clients**, ACP Storm repair is a contractor completing repairs only. ACP Storm Repair representatives are not Public adjusters. ACP Storm Repair representatives are not legal advisers. Any legal advice given, quoted, spoken of or referenced to is as advisement of future possible actions ACP Storm will be taking in team with our clients against insurance companies and their representatives in the event a claim is not paid properly. Therefore legalese is used is not advice but preparation for possible events against insurance companies. Please consult with an attorney on applicability of any quoted laws, bills, acts or policy terms. Regardless ACP Storm always acts in unison and in the best interests of our clients to complete the repairs the best possible way.

ref:\_00DA0HPTa.\_5000f1HXZcB:ref